



These cavities in the laminate are due to poor laminating practice during moulding. They were exposed during peeling and shot blasting and will need to be filled with Easy Fair filler after the application of 1 coat of SAFEGUARD LVP