



Picture courtesy of Advanced Osmosis Technology

**Gel peeling is best done by an experienced operator who will produce a even finish free of bumps and hollows. The dark patches on the peeled surface are areas where the resin has hydrolysed and degraded to form a sticky residue that smells of vinegar. Shot-blasting will remove the soft areas of laminate and key the surface ready for coating.**